


INFORMATION

May 11, 1990
DSD SL 90-12To: **Central Distributors and Diesel Service Dealers**Subject: **Start of Delivery Pickup Flange Installation**

When installing the subject flange in Mack P-7100 injection pump combinations, be certain that the indexing slot points **IN THE DIRECTION OF PUMP ROTATION**. Observe the pump alpha-numeric designation to determine this. Examples are illustrated below.



Thank you for your continued support of Bosch products.

Sincerely,

Richard Lindberg
Product Support Manager, Heavy-Duty
AUTOMOTIVE & DIESEL PRODUCTSRobert Bosch Corporation
Sales Group • Department UA/ASV
2800 South 25th Avenue, Broadview, Illinois 60153